

## Wire Connectors

# **Installation Instructions**

Model **P11V** Qty **500 PCS** 

### To be sold only with installation instructions

Installation Instructions:

- 1. Turn off power before installing or removing connectors.
- 2. Strip wires 3/8" (9.5 mm).
- 3. Pre-twisting unnecessary, hold stripped wires together with ends even. Lead stranded wires slightly.
- 4. Align any frayed strands or conductors.
- 5. Push wires into connector and screw on until two twists are visible in wires.

#### FOR USE WITH COPPER TO COPPER

Temperature Rating: 105°C (221°F) Max.

Voltage Rating: 600V Max. building wiring; 1000V Max. in fixtures and signs

Listed as a Pressure-Type Wire Connector on the following **Solid** and/or **Stranded** wire combinations:

#### For UL Listed, CSA and CQC Certified

Wire Connector



## Voltage Rating 600V Max.:

9		
1 #10	1 #12 w/1 or 2 #14	2 #14 w/1 to 3 #16
1 or 2 #12	1 #12 w/1 to 3 #16	2 #14 w/1 to 3 #18
2 or 3 #14	1 #12 w/1 to 4 #18	3 #14 w/1 #16
2 to 4 #16	1 #12 Sol w/5 #18 Sol	3 #14 w/1 or 2 #18
3 or 4 #18	2 #12 w/1 or 2 #18	1 #16 w/2 to 5 #18
1 #10 w/1 #12	2 #12 w/1 #14	2 #16 w/1 to 4 #18
1 #10 w/1 #14	2 #12 w/1 #16	3 #16 w/1 to 3 #18
1 #10 w/1 or 2 #16	1 #14 w/1 to 4 #16	4 #16 w/1 or 2 #18
1 #10 w/1 to 3 #18	1 #14 w/1 to 5 #18	

Voltage Rating 300V Max.:

2 #18 Sol 1#10 w/2 #14 1#16 w/1 #18

Warranty limited solely to repair or replacement; no warranty of merchantability, fitness for a particular purpose or consequential damages



MADE IN CHINA